



Tech Info Library

AppleVision Software Fix for System 7.5 Update 2.0 Read Me(1/97)

Article Created: 6 May 1996

Article Reviewed/Updated: 29 January 1997

TOPIC -----

This article contains the ReadMe file for AppleVision Software Fix. This software should be installed by users who have an AppleVision 1710 Display or AppelVision 1710AV Display and have installed System 7.5 Update 2.0.

DISCUSSION -----

This document contains important information for AppleVision customers.

Who needs to install the AppleVision Software Fix?

=====

If you have an AppleVision Display and you have problems after installing the System 7.5 Update 2.0, you should install the AppleVision Software Fix. This software fixes such problems as:

- When you press the buttons on the front of the display, you see a message that says "No AppleVision Display is connected."
- You have a Power Macintosh 7200 and can't find the Monitors & Sound control panel in the Control Panels folder.
- The Monitors & Sound control panel does not have Geometry, Color, and Monitor Sound buttons. (Note: The Monitor Sound button appears only if you have an AV monitor.)
- You can't change the resolution of the AppleVision Display or you can't open the AppleVision Setup control panel.
- Macintosh Guide does not contain information on the AppleVision Software or Display.

How to install the AppleVision Software Fix

=====

After you install System 7.5 Update 2.0 and AppleVision Software 1.0.x, you can

install the AppleVision Software Fix. Follow these steps:

Step 1

If you don't already have an AppleVision Software Fix floppy disk, then copy the AppleVision Software Fix online disk image to a floppy disk.

Step 2

Insert the floppy disk in your computer and double-click the Installer icon.

What is installed?

=====

68040 or non-PCI

On a 68040 or non-PCI Power Macintosh computer, the installer adds the following files to the System Folder:

- (1) Display Enabler version 2.0.2 is added to the Extensions folder.
- (2) AppleVision Guide Additions version 1.1 is added to the Extensions folder.

PCI-based Power Macintosh

On a PCI-based Power Macintosh computer, the installer adds the following files to the System Folder:

- (1) Monitors & Sound version 1.1 is added to the Control Panels folder.
- (2) SystemAV version 1.1 is added to the Extensions folder.
- (3) °AppleVision version 1.0.4 is added to the Extensions folder.
- (4) Monitors & Sound Guide Additions version 1.0 is added to the Extensions folder.
- (5) AV Monitors Guide Additions version 1.0 is added to the Extensions folder.
- (6) SimpleSound version 1.0 is added to the Apple Menu Items folder.

If you have a 68040 or non-PCI Power Macintosh

=====

When you installed System 7.5 Update 2.0, if you used the Custom Install option to put the Monitors & Sound control panel on a 68040 or non-PCI Power Macintosh, the AppleVision software will not work.

To use the AppleVision Software, follow these steps:

Step 1

Remove the Monitors & Sound control panel from the Control Panels folder.

Step 2

Remove °AppleVision extension from the Extensions folder.

Step 3

Restart the computer.

Step 4

Install AppleVision Software version 1.0.x.

Step 5

Install the AppleVision Software Fix.

These articles can help you locate the software update mentioned here:

- "Where To Find Apple Software Updates" - Lists online services for free Apple software updates.
- "Obtaining Apple Product Support in the USA" - Lists 800 numbers and online services for software updates, Apple support information, and a subset of the Apple Tech Info Library.

This article was published in the Information Alley on 6 May 1996.

Article Change History:

29 Jan 1997 - Added AppleVision 1710 and AppleVision 1710AV to article.

Copyright 1996-97, Apple Computer, Inc.

Keywords: ksts,supt,sys75,kalley

=====

This information is from the Apple Technical Information Library.

ArticleID: TECHINFO-0019713

19970130 08:57:02.00

Tech Info Library Article Number: 19713