



Tech Info Library

ImageWriter II/L: 32K RAM Buffer Is Not Compatible (8/94)

Article Created: 1 August 1994

TOPIC -----

I have a 32K RAM buffer for the ImageWriter II, can I use this in the ImageWriter II/L printer?

DISCUSSION -----

The ImageWriter II/L was redesigned to include a 24K RAM buffer. The 32K RAM buffer designed for the ImageWriter II is not compatible with ImageWriter II/L.

Support Information Services
Copyright 1994, Apple Computer, Inc

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 15973