



Tech Info Library

ImageWriter LQ: Correction to Owner's Guide

This article last reviewed: 30 March 1988

In the ImageWriter LQ Owner's Guide (P/N 030-3068-A), page 190, Figure C-1 should have pin 4 closer to pin 3:

"Female" mini din-8	8	7	6
connector	5	4	3
	2	1	

The numbering is correct for the port on the ImageWriter LQ.
<None>

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2808