



# Tech Info Library

## LaserWriter IINT/NTX: Two Corrections to Owner's Guide

This article last reviewed: 19 April 1988

The "LaserWriter IINT/NTX Owner's Guide" (030-315-A), in the section titled "Using the 25-pin connector," fails to mention that a modem eliminator is needed. The complete connection is:

```
25-pin serial cable
to
25-pin Apple Modem Eliminator (590-0166-A)
to
serial port on LaserWriter II
```

In the subsection "Making the connection," step 6, the MS-DOS commands should be:

```
MODE COM1:96,N,8,1,P
MODE LPT1:=COM1:
```

With the commands in the manual, Shift-\* doesn't print the screen as it's supposed to.

<None>

Keywords: <None>

=====  
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2826