



Tech Info Library

LaserWriter and IBM PS/2: False out of paper Message

Article Created: 20 March 1991

Article Last Reviewed:

Article Last Updated:

TOPIC -----

I have tried connecting an IBM PS/2 to a LaserWriter IINT. After following the directions in the manual (with the corrected "8" instead of "7") I got an error message on the PS/2--"printer out of paper"--although there was some in the paper tray. Where is the problem?

DISCUSSION -----

The MS-DOS COM drivers scan for a particular signal on the RS-232 port for the paper-out condition. Given that, you're probably experiencing some type of cable problem. Most likely, you're missing a jumper on the PS/2 side. Check the DSR or CTS pins.

Also, the LaserWriter IINTX revised manual has about 25 pages of comprehensive details on connecting LaserWriters to IBM-compatibles. Check that for further troubleshooting.

Copyright 1991 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 7618