



Tech Info Library

LaserWriter Pro 630: Not Appearing on Novell 4.1 Network (7/95)

Article Created: 19 July 1995

TOPIC -----

Our Novell server was just recently upgraded from NetWare 4.0.2 to 4.1. Since the upgrade, I am no longer able to see any of the LaserWriter 630 printers on the network even though other printers appear normally. The LaserWriter 630 printers do not appear using ATCON, nor do they appear from the Macintosh clients. What is causing this?

DISCUSSION -----

This situation can occur when NetWare OS versions are upgraded, but the Network Interface Card (NIC) driver on the NetWare server is not the current version. The upgrade from NetWare 4.0.2 to 4.1 involved a number changes to the Appletalk protocol stack and the network interface ODI and supporting NLM's (NetWare Loadable Module), which may require an updated driver. The network interface card manufacturer should be contacted to obtain the most current driver. You should also verify that the driver supports NetWare 4.1.

This article provides information about a non-Apple product. Apple Computer, Inc. is not responsible for its content. Please contact the vendor for additional information.

The Tech Info Library article titled "Locating Vendor Information" can help you search for a particular vendor's address and phone number.

Support Information Services
Copyright 1995, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 18212