



Tech Info Library

LaserWriter Pro 810: Time Out Error Using LocalTalk (3/94)

Article Created: 17 March 1994

TOPIC -----

What causes time out errors when two or more documents are spooled to the LaserWriter Pro 810 connected using AppleTalk?

DISCUSSION -----

When additional RAM is added to the LaserWriter Pro 810, the configuration changes, and the Macintosh needs to be aware of these changes. If extra memory is added without changing the memory configuration, then time out errors occur.

Changing Memory Configuration

- 1) Open the Chooser
- 2) Select the LaserWriter 8 icon
- 3) Click the Setup button
- 4) Click the Configure button
- 5) Change the memory configuration to match the amount installed in the LaserWriter Pro 810

Support Information Services
Copyright 1994, Apple Computer, Inc

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 14978