



Tech Info Library

LaserWriter: Why It Prints Only Two Pages When Using MS-DOS

This article last reviewed: 18 January 1988

If you are printing to a Laserwriter from an MS-DOS machine, and can't print documents more than two pages long (for instance, a ten-page document can only be printed as 5 two-page documents,) it is most likely a "handshaking" problem.

The MS-DOS system and the LaserWriter are not set up for the same kind of handshaking, and the printout is only one buffer-length long.

Make sure that both the printer and the MS-DOS system are set for either DTR or Xon/Xoff handshaking.

Copyright 1990 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2428