



Tech Info Library

Microsoft Windows: LaserWriter Compatibility

This article last reviewed: 13 October 1989

TOPIC -----

Is it true that Microsoft's "Windows" needs ROM 2.0 or greater present in the LaserWriter IINTX to function properly. Is there another issue here?

DISCUSSION -----

The issue is not the version of the ROM but the version of PostScript residing in the ROMs. The original LaserWriters started with ROM version 1 or PostScript version 23. The second ROM set for the original LaserWriters is known as ROM version 2 or PostScript version 38. The third ROM set is known ROM version 3 or PostScript version 47.

The LaserWriter IINT and LaserWriter IINTX both use PostScript version 47. However, the ROMs in the LaserWriter IINT and LaserWriter IINTX have additions to the ROMs, which are in the original LaserWriters. The ROMs in the LaserWriter IINT and LaserWriter IINTX are considered ROM version 1.0 for the LaserWriter IINT and LaserWriter IINTX, although the PostScript version is 47.

Microsoft Windows requires PostScript version 38. In the older LaserWriters, version 38 of PostScript was also known as version 2 of the ROM.

The latest versions of Windows (Windows 2.11) and its PostScript driver (PostScript driver 3.1) do not suffer from this problem and will print to a LaserWriter II successfully.

Copyright 1989 Apple Computer, Inc.

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 4136