



# Tech Info Library

## Workgroup Server 8550:Does Not Support Half-Height Drives (5/96)

Article Created: 21 May 1996

TOPIC -----

Does Apple officially support the installation of 1/2 height drives in the hard drive bracket assembly in the Workgroup Server 8550? I am asking because I want to add a second hard drive; not replace the original drive.

DISCUSSION -----

No, Apple will not officially support the installation of half-height hard drives in the Workgroup Server 8550. The drive carrier in the Workgroup Server 8550 computer will only support the addition of a third-height hard drive.

NOTE: Even though it may be possible to physically fit a half-height hard drive in the bracket itself, the screw holes which mount the drive to the bracket will not match up. If you do somehow manage to install this type of drive, Apple will not support its use in your Workgroup Server 8550.

Copyright 1996, Apple Computer, Inc.

Keywords: supt,hts

=====

This information is from the Apple Technical Information Library.

19960522 08:06:38.00

Tech Info Library Article Number: 19833