



Tech Info Library

Energy Saver v2.0.1: Server Restart Option (9/96)

Article Created: 27 August 1996

Article Reviewed/Updated: 3 September 1996

TOPIC -----

I have two Workgroup Servers, and we just had a power outage. One server automatically restarted and the other server did not. Why is that?

DISCUSSION -----

The Energy Saver control panel v2.0.1 has a Server Setting option in the Preferences menu. The "Restart automatically after a power failure." option is not selected. If this option is selected and the server still does not restart, throw out the Energy Saver Preferences in Preferences Folder and reset preferred Energy Saver options.

Article Change History:

03 Sep 1996 - Added keyword.

Copyright 1996, Apple Computer, Inc.

Keywords: ksts,kalley

=====

This information is from the Apple Technical Information Library.

19960905 08:06:22.00

Tech Info Library Article Number: 20332