



# Tech Info Library

## ROM version 1.707-02 Problem of Supra Fax Modems (6/93)

Article Created: 17 June 1993

TOPIC -----

This article describes a ROM problem, version 1.707-02, in Supra Fax Modems.

DISCUSSION -----

There is a known problem in the ROM, version 1.707-02, of newer V.32bis Supra Fax modems. Two of these modems will not talk to each other over AppleTalk Remote Access (ARA). Older V.32bis Supra Fax modems seem to work fine. Contact Supra Corporation for information.

To locate a vendor's address and phone number, use the vendor name as a search string.

Copyright 1993, Apple Computer, Inc.

Keywords: <None>

=====  
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 12575