



Tech Info Library

When ADB Keyboards Do Not Function Properly

This article last reviewed: 28 September 1989

TOPIC -----

What causes a keyboard to act sporadically on a given machine? I have a Macintosh IICx, and any keyboard connected to it eventually begins to act strangely. It throws characters and mistypes them. When ports are changed, the same thing happens. Is there anything wrong with the system file?

DISCUSSION -----

We suspect that the problem resides in the logic board of this specific Macintosh. Since using the other ADB port on this specific board did not work, we suggest running diagnostics on the logic board. An alternative would be to replace the board to see if the problems remain. It is quite likely that the hardware that controls the Apple Desktop Bus is intermittently failing.

If this does not resolve the problem, you can try using the Control Panel and resetting parameter RAM. You should also set the keyboard settings to their slowest level and then back to the desired settings. Parameter RAM does contain settings that can affect the performance of the keyboard.

Copyright 1989 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 4551