



# Tech Info Library

## Macintosh 128K/512K: Cable to RS-232 printer (10/94)

Article Created: 4 December 1984

Article Reviewed/Updated: 13 October 1994

TOPIC -----

What cable do I need in order to connect a Macintosh 128K or 512K to an RS-232 printer like the original ImageWriter?

DISCUSSION -----

(Part number 590-0169)

DB-9 Connector (Male)	DB-25 Connector (Male)
1 -----	1
3 & 8 -----	7
5 -----	3
7 -----	20
9 -----	2

Article Change History:

13 Oct 1994 - Reviewed for technical accuracy, revised formatting.

Support Information Services

Copyright 1984-94, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1039