



Tech Info Library

Macintosh SE-to-Macintosh SE/30 Upgrade: Drive Issues

Article Created: 6 December 1989

Article Last Reviewed: 23 August 1991

Article Last Updated: 23 August 1991

TOPIC -----

I have a Macintosh SE with two floppy drives. Can I upgrade to a Macintosh SE/30 with one Apple SuperDrive (formerly Apple FDHD) and one 800K floppy drive?

DISCUSSION -----

It is not possible to upgrade a Macintosh SE with two floppy drives to a Macintosh SE/30 with one SuperDrive and one 800K floppy drive. This is because the Macintosh SE/30 logic board has only one internal floppy-drive connector. When upgrading a dual floppy drive Macintosh SE, you must remove one of the internal floppy drives.

It is possible to upgrade to the SuperDrive without also upgrading to the Macintosh SE/30 logic board. In this case it would be possible to retain both floppy drives.

Copyright 1989, 1990, 1991 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 4752