



# Tech Info Library

## **Pwr Mac 6360/Performa 6400: Pulse Dialing Does Not Work (3/97)**

Article Created: 31 January 1997

Article Reviewed/Updated: 3 March 1997

TOPIC -----

I cannot use pulse dialing to fax from the Apple Telecom software. It always defaults to tone dialing.

DISCUSSION -----

Apple is aware of the issue. However, at this time there are no known workarounds, and there is no date estimates when this will be corrected in the Telecom software.

Article Change History:

03 Mar 1997 - Added current information.

Copyright 1997, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

ArticleID: TECHINFO-0020909

19970304 08:21:56.00

Tech Info Library Article Number: 20909