



Tech Info Library

Power Macintosh 7500 and 8500: Technical Info Update (12/95)

Article Created: 07 December 1995

TOPIC -----

This article contains an update to the Technical Information booklet that came with your Power Macintosh 7500 or 8500 series computer.

DISCUSSION -----

The following table replaces the table in the section titled, "Assigning SCSI ID Numbers":

Begin_Table

SCSI bus	SCSI ID	Device
-----	-----	-----
Internal*	0	factory-installed hard disk
	1	available
	2	available
	3	factory-installed CD-ROM drive (optional)
	4	available
	5	available
	6	available
	7	Power Macintosh computer
External	0	available
	1	available
	2	available
	3	available
	4	available
	5	available
	6	available
	7	Power Macintosh computer

End_Table

*Although five or six SCSI ID numbers are available for assignment, only one other SCSI device can be connected to the internal SCSI chain because of space limitations.

The following table replaces the table in the section titled, "Audio and

Telecommunication Devices":

Begin_Table

Device	Voltage	Current	Power
-----	-----	-----	-----
Microphone	+5 V	20 mA	100 mW
GeoPort telecom adapter	+5 V	500 mA	2.5 W
S-video input connector	+12 V	250 mA	3.0 W

Support Information Services

Copyright 1995, Apple Computer, Inc.

Keywords: kppc,kmanerr

=====

This information is from the Apple Technical Information Library.

19960522 08:06:38.00

Tech Info Library Article Number: 19030