



Tech Info Library

Power Macintosh 7500 & 8500: Using a DAV Card (12/95)

Article Created: 19 December 1995

TOPIC -----

I have a Power Macintosh 8500 computer with a third-party DAV (Digital Audio/Video) card installed. Ever since installing the DAV card the images on the screen appear distorted.

DISCUSSION -----

Apple is aware of and has resolved this DAV issue, which affects a small number of Power Macintosh 7500 and 8500 computers. For assistance resolving this issue, contact an Apple-authorized service provider.

Support Information Services

Copyright 1995-96, Apple Computer, Inc.

Keywords: hts,kppc

=====
This information is from the Apple Technical Information Library.

19961029 07:52:30.00

Tech Info Library Article Number: 19096