



# Tech Info Library

## Power Macintosh: AV Upgrade and Composite Video Ports (3/94)

Article Created: 10 March 1994

TOPIC -----

This article describes the missing composite video ports when upgrading a Macintosh Quadra 840AV or 660AV to a Power Macintosh.

DISCUSSION -----

When a Macintosh Quadra 840AV or 660AV is upgraded to a Power Macintosh AV, the composite video ports will be missing.

These ports are provided via a composite video adapter which is connected to the S-video ports of the AV card.

Support Information Services  
Copyright 1994, Apple Computer, Inc.

Keywords: kppc, supt

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 14861