



Tech Info Library

Power Macintosh: 1 MB and 2 MB SIMMs not supported (5/94)

Article Created: 24 May 1994

TOPIC -----

Does the Power Macintosh support 1 MB or 2 MB 72-pin non-composite SIMMs?

DISCUSSION -----

Apple has not tested 1 MB or 2 MB SIMMS in Power Macintosh systems and therefore cannot support their use.

What this means is that there is no technical reason they should fail, however Apple cannot guarantee that you will not encounter problems in using these SIMM sizes.

Support Information Services
Copyright 1994, Apple Computer, Inc

Keywords: kppc

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 15454