



# Tech Info Library

## Power Macintosh: No Video w/ SCSI External Devices Attached 9/94

Article Created: 09 September 1994

TOPIC -----

There have been reports that Power Macintosh computers sometimes fail to display video via the High Performance Video Card (HPV) or the AV video card when external SCSI devices are powered on.

This article discusses a possible cause for this problem.

DISCUSSION -----

Reference the following configuration:

Power Macintosh 8100/80 with CD-ROM and 500 megabyte HD  
Apple 16" Color Display attached to the HPV card  
Ehman Video Card and monochrome display  
MicroTek Scanner (ID 6)  
APS Syquest (ID 2)  
Bernoulli (ID 4)

The computer would not produce video on the monitor attached to the HPV card if any one of the external SCSI devices were powered on before starting the computer. The display attached to the Ehman card would work fine. The same SCSI chain worked fine on another Power Macintosh 8100.

To troubleshoot, we checked SCSI ID's, cable lengths, and termination. We also zapped the PRAM and booted from the Power Macintosh System Software CD. The problems persisted.

As a last resort, we reseated the HPV card and the problem went away. The Macintosh would display video on the 16" display with all SCSI devices attached and the devices worked properly.

Reseating the HPV card on a Power Macintosh should only be performed by an Apple Authorized Service Provider as damage to the computer's logic board can result if not done properly.

Support Information Services  
Copyright 1994, Apple Computer, Inc

Keywords: kppc,hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 16233