



# Tech Info Library

## Power Mac Upgrade Card Not Switching To PowerPC Mode (10/96)

Article Created: 28 March 1994

Article Reviewed/Updated: 2 October 1996

TOPIC -----

I cannot get the Power Macintosh Upgrade Card to come up in Power Macintosh mode.

DISCUSSION -----

When the control panel has been switched to the correct mode, you must then Shut Down (from the Special menu) and power on the computer. A restart will not work because the computer's Application Specific Integrated Circuits (ASIC) do not get reset unless they are powered off. A hard reset (Control-Command-Power) will reset the ASICs, but you can also corrupt the System file by doing this.

In addition, resetting the PRAM (Option-Command-P-R) at startup will bring the system up in 68000 mode regardless of the setting.

Article Change History:

02 Oct 1996 - Reworded for clarity.

Copyright 1994-96, Apple Computer, Inc.

Keywords: kppc,supt

=====

This information is from the Apple Technical Information Library.

19961003 07:27:49.00

Tech Info Library Article Number: 15030