



Tech Info Library

Power Macintosh: Upgrades from Other Macintosh Models (8/95)

Article Created: 16 February 1995

Article Reviewed/Updated: 16 August 1995

TOPIC -----

The following compares all currently available upgrades to Power Macintosh.

DISCUSSION -----

Begin_Table

Current Macintosh model	Current clock speed	Speed with Power Macintosh Upgrade Card	Speed with: Macintosh Processor Upgrade
Quadra 950	33 MHz	66 MHz !	N/A
Quadra 900	25 MHz	50 MHz !	N/A
Quadra 840av	40 MHz	N/A	N/A
Quadra 800	33 MHz	66 MHz !	N/A
Quadra 700	25 MHz	50 MHz !	N/A
Quadra 660av	25 MHz	N/A	N/A
Quadra 650	33 MHz	66 MHz !	N/A
Quadra 630	33 MHz	66 MHz !	66 MHz
Quadra 610	25 MHz	50 MHz	N/A
Quadra 605	25 MHz	N/A	50 MHz
Centris 660av	25 MHz	N/A	N/A
Centris 650	25 MHz	50 MHz	N/A
Centris 610	20 MHz	40 MHz	N/A

Macintosh IIfx	16 MHz	N/A !	N/A

Macintosh IIfx	32 MHz	N/A !	N/A

Macintosh IIfx	25 MHz	N/A !	N/A

Macintosh IIfx	20 MHz	N/A !	N/A

LC 630	33 MHz	N/A !	66 MHz

LC 575	33 MHz	N/A !	66 MHz

LC 475	25 MHz	N/A !	50 MHz

Performa 630 series	33 MHz	N/A !	66 MHz

Performa 600	32 MHz	N/A	N/A

Performa 575, 577 & 578	33 MHz	N/A !	66 MHz

Performa 475 & 476	25 MHz	N/A !	50 MHz

End_Table

KEY:

! - Separate Upgrade Card offered by DayStar Digital.

NOTES:

- Power Macintosh Upgrade Cards are customer installable.
- Macintosh Processor Upgrade
 - Comes with PowerPC 601 Processor with floating-point processor and 256K level-2 cache that is expandable to 1MB.
 - Must be installed by an Apple authorized service provider.

Article Change History:

16 Aug 1995 - Modified format for ease of viewing.
 27 Jul 1995 - Reviewed for grammatical errors.
 23 May 1995 - Removed Logic Board upgrades from article.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Keywords: kppc

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17205