



Tech Info Library

System 7.5.3 Rev 2: Important SW Updates Isn't Included (6/96)

Article Created: 3 June 1996

Article Reviewed/Updated: 6 June 1996

TOPIC -----

I have a PCI-based Power Macintosh computer, which came pre-installed with System 7.5.3. I'm planning on installing System 7.5.3, Revision 2, but I need to know if the software in the Important Software Updates folder is included with this updater.

DISCUSSION -----

No, System 7.5.3, Revision 2 does not provide the Drive Setup update, AppleGuide update, and Ethernet Compatibility extension included in the Important Software Updates folder on PCI-based Power Macintosh computer with System 7.5.3 pre-installed. These updates are considered to be part of System 7.5.3 for these computers and must be installed in addition to System 7.5.3, Revision 2.

Article Change History:

07 Jun 1996 - Changed distribution status.

06 Jun 1996 - Modified title.

Copyright 1996, Apple Computer, Inc.

Keywords: sys75,kppc

=====

This information is from the Apple Technical Information Library.

19960606 16:20:01.00

Tech Info Library Article Number: 19937