



Tech Info Library

PowerBook: Battery DA Manual Correction (6/92)

Article Created: 30 October 1991

Article Reviewed/Updated: 1 June 1992

TOPIC -----

The Battery DA is programmed to "lose" the lightning bolt when the battery goes into trickle charge. This isn't an intuitive course for the Battery DA to follow. The user's manual on page 96 says that "when the power adapter is plugged in, the Battery DA will show a lightning bolt through the battery graphic." This is not happening.

DISCUSSION -----

The PowerBook user manuals are being updated to address errors that were discovered, including the one you've identified. Current product inventory will still have the original manuals.

Support Information Services
Copyright 1991, Apple Computer, Inc.

Keywords: kpbook

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 9082