



Tech Info Library

Use MacLink Plus 3.X With Wang VS Release 7

This article last reviewed: 13 October 1989

TOPIC -----

I am using MacLink Plus/Wang VS 2.02 to connect the Macintosh to a Wang VS model 15 running the VS release 7 operating system for terminal emulation using direct cable to an ADC port. When connection is established, I get the logon VS screen--but that's all. The characters entered for userid and password don't seem to be accepted by the VS; the Macintosh beeps with each keystroke.

DISCUSSION -----

We talked with DataViz Technical Support, and they confirmed that versions of MacLink Plus prior to version 3 do not work properly with VS release 7. They suggested that you should upgrade to the latest version which is 3.06. According to DataViz, they currently have a free upgrade program in place.

For more in-depth support on their product, we suggest you contact them directly. For more their addresses and numbers, search the Tech Info Library under "DataViz."

Copyright 1989 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 4783