



Tech Info Library

What's New In Apple HD SC Setup 7.3.5? (6/95)

Article Created: 19 April 1995

Article Reviewed/Updated: 28 June 1995

TOPIC -----

I just downloaded Apple HD SC Setup 7.3.5 from an online service, but the Read Me document did not explain what is new?

DISCUSSION -----

Apple HD SC Setup was updated to provide support for 4 GB (gigabyte) Apple hard disk drives. Apple HD SC 7.3.5 now handles the initialization and mounting of 4 GB drives. A 4 GB hard drive is available with the Workgroup Server 8150/110 and 9150/120*. Each of those systems (and the Power Macintosh 8100/110) can accommodate volumes up to 4 GB. The HD SC Setup 7.3.5 utility and the hard disk driver that is installed when a user performs an "Update Driver" command with this utility is appropriate for use on all Macintosh computers.

Additionally, Apple HD SC Setup 7.3.5 adds a new supported feature letting users partition their Apple hard drive into additional Macintosh volumes.

By choosing Partition from the opening dialog box in Apple HD SC Setup 7.3.5, the user is given the following options for a partition:

- Maximum Macintosh
- Minimum Macintosh
- 50% Macintosh
- Standard A/UX
- A/UX System, 40MB Macintosh, Free A/UX
- A/UX System, Maximum Macintosh
- Maximum Free A/UX
- 50% Macintosh, 50% A/UX
- 10MB ProDOS, Maximum Macintosh

If the user chooses Custom from within the Partition dialog box and drags in gray area to create a new partition, the user is given the following options for a custom partition:

- Macintosh Volume
- Scratch
- A/UX Autorecovery
- A/UX Root&Usr slice 0

- A/UX Swap slice 1
- A/UX Root slice 0
- A/UX Usr slice 2
- Free A/UX slice 3
- Free A/UX slice 4
- Free A/UX slice 5
- •Additional Mac Volume•
- Misc A/UX
- ProDOS Volume

* NOTE: Although the Server configurations with 4 GB drives mentioned above do not appear specifically on the Apple Products list, these configurations will be available to customers under Apple's Build-To-Order purchase program. For more information regarding Build-To-Order configurations, customers may call 1-800-GO APPLE.

These articles can help you locate the software update mentioned here:

- "Where To Find Apple Software Updates" -- Lists online services for free Apple software updates.
- "Obtaining Apple Product Support in the USA" -- Lists 800 numbers and online services for software updates, Apple support information, and a subset of the Apple Tech Info Library.

Article Change History:

28 Jun 1995 - Added information about multiple Macintosh volume support.

27 Apr 1995 - Corrected minor typo.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Keywords: supt

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17621