



Tech Info Library

LaserWriter IIf: Misconfigured Memory Error (2/95)

Article Created: 23 November 1992

Article Reviewed/Updated: 02 February 1995

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

What causes a LaserWriter IIf to exhibit a steady Ready/Wait, blinking Paper Jam and steady Paper Out light condition on power-up?

DISCUSSION -----

The LaserWriter may have misconfigured memory. Make sure the memory configuration is correct. If the configuration is correct, perform the LaserWriter IIf troubleshooting procedures found in your Service Source CD.

Article Change History:

02 Feb 1995 - Changed access privileges of article.

Support Information Services

Copyright 1992-95, Apple Computer, Inc.

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 10754