



# Tech Info Library

## Macintosh Performa: System Software Requirements (2/95)

Article Created: 20 August 1993

Article Reviewed/Updated: 09 February 1995

\* RESTRICTED: Apple Internal and Support Providers Only \*  
Not For General Public Release

TOPIC -----

I need a system software compatibility chart that covers the entire Macintosh Performa family.

DISCUSSION -----

Use the following chart to determine which version of system software you should be using on your Macintosh Performa computer:

KEY:

! Not tested/not recommended

\$ Will work, but not recommended

\* Works with this version of system software

() Works with this version of system software, but requires a Macintosh System Enabler

\*\* Shipped with this version of system software

Performa	7.1P5	7.1P3	7.1P2	7.1P1	7.1P	7.0.1P	7.1	7.0.1	7.0	6.0.8
200	*	*	*	*	*	**	*	*	*	*
400	*	*	*	*	*	**	*	*	*	*
405	*	*	*	*	*	**	*	*	*	*
410	*	**	\$	\$	\$	\$	*	*	*	*
430	*	*	**	\$	\$	\$	*	*	*	*
450	*	*	**	\$	\$	\$	()	!	!	!
460	*	**	!	!	!	!	!	!	!	!
466	*	**	!	!	!	!	!	!	!	!
467	*	**	!	!	!	!	!	!	!	!
475	*	**	!	!	!	!	()	!	!	!
476	*	**	!	!	!	!	()	!	!	!

550	*	**	!	!	!	!	!	!	!	!
600	*	*	**	**	**	!	( )	!	!	!
630	*	!	!	!	!	!	!	!	!	!
611x	!	!	!	!	!	!	!	!	!	!

NOTES:

- All Performa computers will function with System 7.5 provided sufficient memory is available.
- The Performa 200, 400, 405, 410 and 430 do NOT require a System Enabler to run Performa or Macintosh System Software.
- The Performa 450, 460, 466 and 467 require System Enabler 308 to run Performa System Software. The Performa 450 will run Macintosh System Software with Macintosh System Enabler 003.
- The Performa 475 and 476 require System Enabler 364 to run Performa System Software. The Performa 475 and 476 will run Macintosh System Software 7.1 with Macintosh System Enabler 065. Performa 550 requires Enabler 332.
- The Performa 600 requires System Enabler 304 to run Performa System Software and Macintosh System Enabler 001 to run Macintosh System Software 7.1.
- As indicated, Macintosh Performa models will run with some standard versions of system software (those without a "P"), though some models may need an appropriate enabler.

Article Change History:

- 09 Feb 1995 - Revised for System 7.5.
- 08 Mar 1994 - Corrected the alignment of the chart.
- 07 Jan 1994 - Corrected Enabler number for Performa 550.

Support Information Services

Copyright 1992-1995, Apple Computer, Inc.

Keywords: sys7

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 10986