



Tech Info Library

Macintosh 21 Color Display: Rapid Low Intensity Flashing (3/93)

Article Created: 9 March 1993

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

The brightness level on my Macintosh 21" Color Display intermittently flickers or flashes rapidly. What causes this?

DISCUSSION -----

You must remove diode V503 from the CRT board. Here's how:

- 1) Unplug the monitor's power cord.
 - 2) Remove the monitor cabinet and the metal shield that shields the CRT board.
 - 3) While viewing the solder side of the CRT board, find the designation V503 in the lower-right quadrant of the CRT board.
 - 4) Unplug the CRT board from the CRT socket and clip out diode V503.
 - 5) Reinstall the CRT board and test the monitor. It should operate normally.
- Copyright 1993, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 11680