



Tech Info Library

Macintosh 800/840AV/8100: Power Supply Pinouts (11/95)

Article Created: 12 September 1994

Article Reviewed/Updated: 10 November 1995

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

What are the pinouts for the Macintosh Quadra 840AV power supply 22-pin Output connector?

DISCUSSION -----

The following figure lists the pinouts of the output connector for the Quadra 800/840AV/Workgroup Server 80/Power Macintosh 8100 Power Supply (Apple p/n 661-1687).

Note: See the Tech Info Library article, "Power Macintosh 8100: Power Supply Voltage Test" for related information.

Begin_Table

| PIN | OUTPUT | | OUTPUT | PIN |
|-------|--------|-----|---------|----------------|
| ----- | | | | |
| 11 | -12V | --> | • • | <-- +12V 22 |
| 10 | N/C | --> | • • | <-- /PFW 21 |
| 9 | GND | --> | • • | <-- GND 20 |
| 8 | GND | --> | • • | <-- GND 19 |
| 7 | GND | --> | • • | <-- GND 18 |
| 6 | GND | --> | • • | <-- GND 17 |
| 5 | GND | --> | • • | <-- +5V 16 |
| 4 | +5V | --> | • • | <-- +5V 15 |
| 3 | +5V | --> | • • | <-- +5V 14 |
| 2 | +5V | --> | • • | <-- +5V 13 |
| 1 | +5V | --> | • • | <-- 5V_TRKL 12 |

End_Table

Article Change History:

10 Nov 1995 - Updated with other article reference.

Support Information Services
Copyright 1994, Apple Computer, Inc

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 16254