



# Tech Info Library

## Multiple Scan Display: High Pitched Whine at Highest Res. (4/95)

Article Created: 20 April 1995

TOPIC -----

I've noticed a high pitched whine emanating from my Multiple Scan 17 display. It seems to get worse when I change to the highest resolution. What can be done to resolve this issue?

DISCUSSION -----

If the screen on the display is operating normally while the noise is occurring, then the problem is most likely related to a sub-harmonic of the horizontal sweep frequency--that is why the noise occurs only in one resolution.

This suggests that the flyback transformer is probably the culprit. Replacement of the main board is the best way to resolve this issue; there are no adjustments to reduce or remove the noise.

Support Information Services  
Copyright 1995, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17634