



Tech Info Library

Apple Color Printer: Uneven Margins in Printer Driver (4/95)

Article Created: 12 April 1995

TOPIC -----

When I print from my Apple Color Printer, the top and bottom margins are shifted slightly. How can I correct this?

DISCUSSION -----

When printing from the original Apple Color Printer, the top margin may actually print 1/8-in. less than expected, and the bottom 1/8-in. larger. For example, a margin of 1-in. on all sides may yield a top margin of 7/8-in. and the bottom 1 1/8-in.

The problem is actually with the Apple Color Printer driver. There are no plans to revise the Apple ColorPrinter driver. However, one possible solution is contact GDT Softworks. GDT Softworks makes PowerPrint. PowerPrint contains a newer version of the Apple Color Printer Driver. This may resolve the problem, however Apple does not guarantee this solution).

Another solution would be to adjust for the margin difference through the application being used.

The problem may be more prevalent when printing from Postscript programs.

The Tech Info Library article titled "Locating Vendor Information" can help you search for a particular vendor's address and phone number.

Support Information Services
Copyright 1995, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17583