



Tech Info Library

Apple IIGS: Known ImageWriter LQ and Bin Selection Problem

This article last reviewed: 9 June 1989

Some LocalTalk users are unable to select paper bins on the cut-sheet feeder with the Chooser. These users get a "paper out" error message when using the LocalTalk ImageWriter LQ with an Apple IIGS. Yet, when the ImageWriter LQ is directly connected to the Apple IIGS, bin selection works fine. A typical system giving rise to this problem includes:

- an Apple IIGS with LocalTalk PC Card
- a LocalTalk ImageWriter LQ
- a cut-sheet Feeder

The problem appears to be with the LocalTalk interface for the ImageWriter LQ. The escape codes required for changing the bins get stripped from the packets sent to the ImageWriter. At this time, there is no known workaround for this problem.

Copyright 1989 Apple Computer, Inc.

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 4081