



# Tech Info Library

## ImageWriter LQ: Resetting ASCII Escape Codes

Article Created: 14 June 1991

Article Last Reviewed:

Article Last Updated:

TOPIC -----

I'm using an ImageWriter LQ with a Macintosh IIsi. I want to reset the ImageWriter LQ to print 8 1/2-inch pages at 10 cpi character setting.

My document is from a program called Pacershare on a DEC VAX. I thought I had inserted the correct ASCII escape codes (from the ImageWriter LQ owner's manual) as the first commands in the document. The ImageWriter LQ does not respond to these codes, and prints only in the default 12 cpi, 11-inch page length. Any suggestions?

DISCUSSION -----

All escape codes are overruled by the ImageWriter LQ driver. Your desired page description must be set up in the application program's Page Setup. Copyright 1991 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 8426