



# Tech Info Library

## Laserwriter IISC Requires System V4.3

This article last reviewed: 3 March 1988

If you are having trouble printing to the Laserwriter IISC from AppleLink, and you have the correct driver to print from other software, you may be using the wrong System file.

You MUST use System version 4.3 with the LaserWriter IISC.  
Copyright 1988 Apple Computer, Inc.

Keywords: <None>

=====  
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2734