



Tech Info Library

LaserWriter Pro 810: 802.2 Novell Ethernet Frame Types (2/95)

Article Created: 16 February 1995

TOPIC -----

Does the LaserWriter Pro 810 support 802.2 Novell Ethernet frame types?

DISCUSSION -----

The LaserWriter Pro 810 does not support 802.2 frame types, only 802.3 and Ethernet_II. For this printer to function in a Novell NetWare environment (and 802.2 is the default with Netware 3.12 and 4.x), the NetWare autoexec.ncf file must have an entry for one of these other protocols to support a LaserWriter Pro 810 printer.

Support Information Services
Copyright 1995, Apple Computer, Inc.

Keywords: knts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17204