



Tech Info Library

Installing 810 Software on Sparc Station (4/94)

Article Created: 20 April 1994

TOPIC -----

Software installation fails when installing on a Sun Sparc Classic running Solaris 2.2. Software installs properly on a Sun Sparc 10 model 41 running SunOS.

DISCUSSION -----

There was a minor problem with the first release of LaserWriter Pro 810 install utilities for compiling the codes on SunSparc station running Solaris 2.2 or 2.3. There is a newer version which is available. Users should run the "eninstall" with the -b option to install on the system without compiling the codes.

The LaserWriter Pro 810 Utilities with pre-compiled executable binaries for Sun Solaris 2.2 or 2.3 has been posted to on-line services.

These articles can help you locate software updates mentioned here:

- Where To Find Apple Software Updates
Lists online services for "free" Apple software updates
- Obtaining Apple Product Support in the USA
Lists 800 numbers and online services for software updates, Apple support information, and a subset of the Apple Tech. Info. Library

It is also available in ftp.support.apple.com via Internet anonymous ftp.

Support Information Services
Copyright 1994, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 15163